

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003053**Date Inspected:** 04-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1430**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2230**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use: Yes No N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed: Yes No N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up: Yes No N/A
Approved Drawings:	Yes	No	N/A	Approved WPS: Yes No N/A
				Delayed / Cancelled: Yes No N/A
Bridge No:	34-0006	Component:	Tower and OBG Fabrication	

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. The QA Inspector observed the following:

No closed rib Production Monitoring Tests Macro Etch specimens were presented to the QA Inspector for inspections this shift.


Bay 1

The QA Inspector performed random ultrasonic inspections of OBG closed rib Diaphragm plate weld DP-551-001-250. Items observed appear to comply with project specifications. See the TL-6027 "Ultrasonic Test Report" dated today and the photograph below for additional information.

ZPMC 'Notification of Witness Inspection' document #00484 states DP551-001-245, DP551-001-244 and several other similar welds will be ultrasonically inspected by QC Personnel starting at 1930 hours. The QA Inspector observed the original "UT Reject" markings are on these welds and the QA Inspector did not observe where ZPMC QC UT personnel had marked these welds as being "UT Acceptable". See the photo below for additional information.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No significant conversations occurred.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Patrick Lowry (858) 344-2712, who represents the Office of Structural Materials for your project.

Inspected By:	Dawson,Paul	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
